

## Document Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Vehicles affected:

P11: 12C, 12C Spider, 650S, 650S Spider, 625C, 625C Spider, 675LT, 675LT Spider

P12: P1

P13: 540C, 570S, 570S Spider, 570GT, 600LT, 600LT Spider

P14: 720S, 720S Spider

Location: Chassis - Brakes

Concern: No diagnostics required if the DTC B132129 is logged in SBC with no customer related complain.

Condition: N/A

## Diagnostic Trouble Codes

SBC:

B132129 Brake Switch Adjustment Fault : Signal Invalid

ESP:

C181D02 plaus.failure 1 pressure sensor MC1 vers. BLS. defect BLS

## Measure

The DTC "B132129 Brake Switch Adjustment Fault : Signal Invalid" logged in the SBC, can be ignored if no other brake light switch related DTC is logged in the ECM and/or ESP.

If DTC "C181D02 plaus.failure 1 pressure sensor MC1 vers. BLS. defect BLS" is logged in ESP along with the above DTC, then proceed and check the adjustment of the brake light switch as per SIS instructions.

## MTI Updates Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.