

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Vehicles affected: P14: 720S, 720S Spider, 765LT, P15: Senna

Location: Chassis - Suspension

Topic: Accelerometer sensor failure after suspension repairs due to excessive vibration

Condition: Sensor failure

Diagnostic Trouble Codes: N/A

Measure

Due to the sensitivity of the accelerometer sensors on the front and rear suspension uprights, the use of air/impact tools can result in the failure of these sensors if they are not removed first.

As a result, we advise removing these sensors **before** any suspension work is carried out, that will involve impact or air tools to be used.

Should suspension work be carried out without the removal of the accelerometer sensors first, resulting in their failure, the warranty claim for sensor replacement may be rejected.

Parts Information

N/A

Attachments

N/A

KA Update Information

27/04/2021 - KA Review

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.