

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Powertrain

Topic: WCAC Inlet to Top Hose Clash

Condition: In some cases, the WCAC inlet can clash with the top hose on 720S, 765LT and/or GT.

Diagnostic Trouble Codes: N/A

Measure

If a clash is present between the WCAC inlet and the top hose, follow the McLaren Service Portal (MSP) work instruction "Rework – High Temperature Radiator (HTR) Top Hose to Water Charge Air Cooler (WCAC) Inlet Pipe".



If the clash is of concern as per the image below, please raise a technical request (TR).



Parts Information

00RA357	PIPE PROTECTOR
00RB057	CLIP-39-45MM-FEMALE
00RB023	CLIP SPACER-1MM-MALE
00RB120	CLIP-90 DEGREE-FEMALE-20-22

Repair Time

Pipe Protector and Clip Installation – 720S Coupe: 0.50 hrs
Pipe Protector and Clip Installation – 720S Spider: 0.85 hrs
Pipe Protector and Clip Installation – 765LT Coupe: 0.55 hrs
Pipe Protector and Clip Installation – 765LT Spider: 0.85 hrs
Pipe Protector and Clip Installation – GT: 1.45 hrs

Attachments

N/A