

Document Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Vehicles affected: All

Location: Tools - McLaren Diagnostic System

Concern: N/A

Condition: N/A

Diagnostic Trouble Codes

N/A

Measure

McLaren Automotive is pleased to announce the release of MDS version **17.0.1.0042** to the Retailer network.

This replaces the previous version **17.0.0.0042** and all Retailers are required to update their tablets at the soonest opportunity.

The above-mentioned update is available only via an online update.

To complete the installation, ensure internet connection is available, restart the MDS application and follow the update prompts.

Once updated, please see the 'Help Files' section of the MDS for more information on the updates included and vehicle platforms.

The MDS Software Release Notes of version **17.0.1.0042** is available to download [HERE](#)

Warranty Information

N/A

Attachments

N/A

MTI Updates Information

11/04/2019

Latest MDS Release Notes Released

28/05/2019

Latest MDS Release Notes Released

18/12/2019

Latest MDS Release Notes Released

04/02/2020

Latest MDS Release Notes Released

18/03/2020

Latest MDS Release Notes Released

27/05/2020

Latest MDS Release Notes Released

15/07/2020

Latest MDS Release Notes Released

04/08/2020

Latest MDS Release Notes Released

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.