

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Chassis / Brakes / Brake Service Procedures

Topic: Clicking noise from CCM brakes

Condition: Intermittent

Diagnostic Trouble Codes: N/A

Measure

Correct cleaning procedure for CCM brakes, in the event of receiving the customer complaint of "clicking" noise from brakes.

Please refer to the relevant repair instruction in SIS under; Chassis - Brakes Front - Brake Service Procedures - Clean/Inspect Discs/Pads.

Parts Information

All parts listed within SIS document

Attachments

N/A

KA Update Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.